Parts needed to mount the OBIT extrusion

Extrusion (A)   Cover (B)   Cover (C)   End cap (D)   LED strip (E)

**Tools needed for mounting:**

- mounting glue

WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.

1. Attach the LED strip (E), insert the cover (C).

A

E

C

2. Insert the cover (B) and end cap (D) Lead out the power cable.

A   B   C

3. Put glue in the mounting channel, connect power, and then insert the extrusion into the mounting channel.