

Parts needed to mount the PDS-4-ALU extrusion



Mounting
bracket (A)



Extrusion (B)



End cap (C)



LED strip (D)



Cover (E)


Tools needed for mounting:

- drill
- screwdriver
- screws


WARNING! All LED strips should be connected to a 12 V or 24 V power supply.

IMPORTANT: The mounting instructions present the basic form of assembly.
More methods and related accessories can be found at www.KlusDesign.com

- 1.** Feed the power cable. Attach the mounting bracket (A) to the mounting surface with screws.



- 2.** Mount the LED strip (D) in the extrusion (B), insert the cover (E) and the end cap (C).



- 3.** Connect power to the LED strip and mount the extrusion (B) in the mounting bracket (A). There are two ways to connect power: through a hole in the extrusion or through the end cap.

